

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2021

Submitted Date:

05/25/2021

Document Number:

700702804

## FIELD INSPECTION FORM

 Loc ID: 335265  
 Inspector Name: Ramsey, Scott  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

1 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 OGCC Operator Number: 10531  
 Name of Operator: GRIZZLY OPERATING LLC  
 Address: 5847 SAN FELIPE #3000  
 City: HOUSTON State: TX Zip: 77057
**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211350	WELL	PR	11/12/1996	GW	045-07110	GIBSON GULCH UNIT 10-30	PR
275515	WELL	TA	09/01/2016	GW	045-10335	GGU VANORDSTRAND 33C-30-691	TA
275526	WELL	PR	07/28/2009	GW	045-10339	GGU VANORDSTRAND 33A-30-691	PR
275565	WELL	PR	10/12/2005	GW	045-10347	GGU VANORDSTRAND 43C-30-691	PR

**General Comment:**

## COGCC Inspection Report Summary

On Tuesday 5/25/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP GGU 10-30, at Location # 3335265 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

C/A's from previous inspection document # 700702131 have been satisfied.

During this inspection the following compliance issues were observed:

1. Location shows signs of lack of stabilization/compaction

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:

<b>Equipment:</b>		corrective date
Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 4	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 5	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 4	
Comment:	One braden head is tied into sales and all Braden heads have a port for manual gauge monitoring	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 211350 Type: WELL API Number: 045-07110 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 275515 Type: WELL API Number: 045-10335 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: last MIT done 9/18/2019

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 275526 Type: WELL API Number: 045-10339 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 275565 Type: WELL API Number: 045-10347 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				
		Culverts				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.  
 1. Location shows signs of lack of stabilization/compaction

Corrective Action: **Install or repair required BMPs**

Date: 06/25/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702812	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440609">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440609</a>