

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2021

Submitted Date:

05/19/2021

Document Number:

696303264

**FIELD INSPECTION FORM**Loc ID 319114 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 70385

Name of Operator: SMITH ENERGY CORP

Address: 12706 SHILOH RD

City: GREELEY State: CO Zip: 80631

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

6 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone          | Email                            | Comment |
|--------------|----------------|----------------------------------|---------|
| ,            |                | dnr_cogccengineering@state.co.us |         |
| Smith, Chris | (970) 330-7034 | smithenergy@live.com             |         |
| Smith, Glenn | (970) 330-7034 | gsmithten@what-wire.com          |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 242917      | WELL | SI     | 06/01/2018  | OW         | 123-10708 | FARNIK-WELD COUNTY 2X | SI          |

**General Comment:**

Follow-Up Inspection to FIR 696300717 dated 10.18.2019

## Location

Overall Good: ☒

|                      |  |       |            |
|----------------------|--|-------|------------|
| <b>Signs/Marker:</b> |  |       |            |
| Type                 | WELLHEAD   |       |            |
| Comment:             | Sign is not legible/fading. See photos             |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.d.            | Date: | 11/18/2019 |
| Type                 | BATTERY  |       |            |
| Comment:             | Tank Battery sign is not legible/faded. See photos |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.e.            | Date: | 11/18/2019 |
| Type                 | TANK LABELS/PLACARDS                               |       |            |
| Comment:             | 50 BBIs Skim Tank - Capacity Missing. See photos   |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.h.            | Date: | 06/18/2021 |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | WEEDS   |       |            |
| Comment:           | Weeds at Tank Battery, Heater Treater and pit. See photos |       |            |
| Corrective Action: | Comply with Rule 606                                      | Date: | 11/18/2019 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | SEPARATOR    |       |  |
| Comment:           | Adequate     |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           | Barbed Wire  |       |  |
| Corrective Action: |              | Date: |  |

|                               |   |       |                 |
|-------------------------------|---|-------|-----------------|
| <b>Equipment:</b>             |   |       | corrective date |
| Type: Bradenhead              | # 0   |       |                 |
| Comment:                      | Bradenhead appears to be NOT plumbed to surface   |       |                 |
| Corrective Action:            | Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) | Date: | 05/31/2021      |
| Type: Vertical Heater Treater | # 1   |       |                 |
| Comment:                      |   |       |                 |

|                                   |     |       |  |
|-----------------------------------|-----|-------|--|
| Corrective Action:                |     | Date: |  |
| Type: Pump Jack                   | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Horizontal Heated Separator | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Deadman # & Marked          | # 4 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |

**Tanks and Berms:**

|                    |   |          |           |         |                       |  |
|--------------------|---|----------|-----------|---------|-----------------------|--|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |  |
| CRUDE OIL          | 2 | 300 BBLs | STEEL AST |         | 40.536370,-103.944180 |  |
| Comment:           |   |          |           |         |                       |  |
| Corrective Action: |   |          |           |         | Date:                 |  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**Facility ID: 242917 Type: WELL API Number: 123-10708 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI - Since 06.01.2018. NO MIT on Record.  
Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42.  
Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 06/18/2021

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding          |                 | Seeding                 |                       |               |                          |         |

Comment: Pasture

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced Water

Lined:

Pit ID:

Lat: 40.535990Long: -103.944160Reference Point: SE

Other: \_\_\_\_\_

Length: 15Width: 10**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Barbed Wire

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <p><b>COGCC Inspection Report Summary</b></p> <p>On Tuesday 05/18/2021 at approximately 13:03, I, Inspector Erica Petrie, conducted a Field Follow-Up Inspection at Smith Energy Corporation, Farnik Weld County 2X at Location #319114 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed: Well and Tank Battery Shut-IN</p> <p>Tank Battery and Wellhead signs have faded and are no longer legible, see photos. Comply with 605 Series Rules for Signage. SAME Corrective Action Date 11/18/2019 is STILL applicable. As issues NOT ADDRESSED.</p> <p>Weeds at Tank Battery, Heater Treater and Pit. See photos. Comply with Rule 606. SAME Corrective Action Date 11/18/2019 is STILL applicable. As issues NOT ADDRESSED.</p> <p>Well is Shut-In Since 06.01.2018. NO MIT on Record. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. Corrective Action Date 06.18.2021 or as Stated by COGCC Engineering Department.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Educational Inspections</p> | petrie | 05/19/2021 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402695583    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434717">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434717</a> |
| 696303265    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434704">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434704</a> |