

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2021

Submitted Date:

05/27/2021

Document Number:

700702815**FIELD INSPECTION FORM**Loc ID 316614 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	832-624-0810	jessica.dooling@exxonmobil.com	
clark, Erin	405-319-3250	erin.k.clark@exxonmobil.com	Lead regulatory coordinator
Sutton, Derek		erin.clark@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288891	WELL	PR	03/01/2021	GW	103-10976	FEDERAL 2S-95-15-42BP	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at XTO Federal 2S-95-15-42BP, at Location # 316614 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also within BLM stipulations area.

During this inspection the following possible compliance issues were observed:

1. Cut slope on location shows signs of lack of stabilization.
2. Lack of battery signage.
3. Debris at well head
4. One (1) dead man is not marked properly
5. Hole in tank battery containment
6. Unused equipment (dehy is disconnected and not in use)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Lack of battery signage.		
Corrective Action:	Comply with rule 605.e	Date:	07/02/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (dehy is disconnected and not in use)		
Corrective Action:	remove unused equipment	Date:	08/27/2021
Type	DEBRIS		
Comment:	random debris at well head		
Corrective Action:	remove debris	Date:	06/04/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 6	
Comment:	One (1) dead man is not marked properly	
Corrective Action:	mark or remove dead man	Date: 07/02/2021
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Dehydrator	# 1	
Comment:	dehy is disconnected and not in use (see unused equipment)	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	well head not on plunger lift	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	water transfer pump	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	OTHER		,
Comment:	open top ground tank is open to Atmosphere				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate		
Comment: Hole in tank battery containment						
Corrective Action: Repair secondary containment						Date: 07/02/2021
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	YES					
Comment:	100 bbl open top ground tank is open to Atmosphere					
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	288891	Type:	WELL	API Number:	103-10976	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
Berms						

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also within BLM stipulations area.
1. Cut slope on location shows signs of lack of stabilization.

Corrective Action: Install or repair required BMPs

Date: 07/02/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702824	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442926