

Inspection Photos

5/26/2021

Operator: CAERUS ENERGY SERVICES LLC #
10668

Location ID: 335669
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 1: Photo of signage at location entrance.

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 2: Photo taken from the east end of the Location, facing south. Photos 2-5 provide an overview of the Location from south, southwest, northwest to north. Photo also shows diesel tank stored on the southeast end of the Location; tank requires removal.

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 3: See comments under photo 2.

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



20210526

Photo 4: See comments under photo 2.

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 5: See comments under photo 2.

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 6: See comments under photo 2.

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 7: Photo taken from the east end of the Location. Photo shows concrete and pipe debris stored on edge of the pad. Debris was documented in inspection #680102840 and was required to be removed by 5/7/2018; debris has not been removed per the corrective action.

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 8: Photo shows various trash debris on the northern interim areas of the Location.

Inspection Photos

Operator Name: CAERUS ENERGY SERVICES LLC # 10668

Location ID: 335669



Photo 9: Photo taken from the northwest corner of the Location. Photo shows stormwater erosion degradation; control measures to protect and stabilize the slopes of the Location, and properly manage runoff from the location are missing or insufficient

Inspection Photos

Operator Name: CAERUS ENERGY SERVICES LLC # 10668

Location ID: 335669



Photo 10: Photo shows unused equipment observed on the west end of the Location. Equipment requires removal pursuant with Rule 606.a

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



20210526

Photo 11: Photo shows unused equipment observed on the west end of the Location. Equipment requires removal pursuant with Rule 606.a

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 12: Photo taken from the northwest corner of the housing unit on the west end of the Location. Photos show batteries improperly stored on the Location.

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 13: Photo taken from the north side of the generator housing. Photo shows tank installed to collect various chemicals from the housing unit. Photo also shows the containment BMP at base of tank; containment BMP is insufficient to prevent and/or contain a spill from the tank.

Inspection Photos

Operator Name: CAERUS ENERGY SERVICES LLC # 10668

Location ID: 335669



Photo 14: See comments under photo 13. Photo shows chemicals within tank. Equipment to prevent entry by wildlife missing.



Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 15: Photo shows tank in front of generator housing; sign or label not posted, or installed in a place where not visible.

Inspection Photos

Operator Name: CAERUS ENERGY SERVICES LLC # 10668

Location ID: 335669



Photo 16: Photo shows tank in front of generator housing; sign or label not posted, or installed in a place where not visible.

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 17: Continued from photo 16. Photo shows wildlife protection screen is not in proper functioning condition. Photo also shows various trash debris within tank.

Inspection Photos

Operator Name: CAERUS ENERGY SERVICES LLC # 10668

Location ID: 335669



Photo 18: Continued from photo 18. Photo shows various trash debris on Location.

Inspection Photos

Operator Name: CAERUS ENERGY SERVICES LLC # 10668

Location ID: 335669



Photo 19: Photo shows various trash debris or unused equipment stored around the generator housing unit.



Inspection Photos

Operator Name: CAERUS ENERGY SERVICES LLC # 10668

Location ID: 335669



Photo 20: Photo shows 3 of the 4 sheds stored on the southwest corner of the Location, as well as various trash debris and unused equipment stored next to the sheds. After review of the Compliance Unit manager, the two white sheds on the right require removal.



Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 21: Photo shows various trash debris observed stored within shed.



Inspection Photos

Operator Name: CAERUS ENERGY SERVICES LLC # 10668

Location ID: 335669



20210526

Photo 22: Photo shows various trash debris observed stored within shed.

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 23: Photo shows 4th shed stored on the southwest end of the Location. After review of the Compliance Unit Manager, shed requires removal.

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC # 10668
Location ID: 335669



Photo 24: Photo shows various trash debris observed stored within shed.