

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2021

Submitted Date:

05/29/2021

Document Number:

701101517

**FIELD INSPECTION FORM**Loc ID 413733 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159981	UIC Disposal	AC	12/30/2020	DSPW	-	SG 914-32D WMFK UIC	AC
412706	WELL	IJ	01/12/2021	DSPW	045-18533	WPX SG 914-32D	AC

**General Comment:**

Routine FIU Inspection

Compliance issues identified with corrective actions and attached photos in this inspection include:

Staining around injection well and stained ground near injection well.

Unmarked deadmen.

500 gallon LPG Propane Tank at well.

CATAFLOW line heater at well.

A follow up will be conducted to confirm corrective actions have been completed.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No API # on well sign.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

 Comment: 911  
 970-285-9377

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Staining around and near injection well.		
Corrective Action:	Clean up stained material and review self inspection processes.	Date:	06/05/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	CATAFLOW line heater at well.		
Corrective Action:	Comply with Rule 610.h.	Date:	06/30/2021
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Unmarked deadmen.		
Corrective Action:	Mark or remove deadmen.	Date:	06/12/2021

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLS	OTHER		,

Comment:	500 gallon LPG Propane Tank at well.	
Corrective Action:	Move equipment to comply with minimum 75 foot setback as per Rule 608.a.8. Comply with Rule 610.e.	Date: 06/30/2021

**Paint**

Condition	Adequate	
Other (Content)	Propane	
Other (Capacity)	500 gallon	
Other (Type)	LPG	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	None			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 159981 Type: UIC Disposal API Number: - Status: AC Insp. Status: ACFacility ID: 412706 Type: WELL API Number: 045-18533 Status: IJ Insp. Status: AC**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101547	Inspection 701101517 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5443898">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5443898</a>