

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2021

Submitted Date:

05/23/2021

Document Number:

701500830

**FIELD INSPECTION FORM**

Loc ID 315097 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10654  
Name of Operator: LASSO OIL & GAS LLC  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone        | Email                       | Comment |
|------------------|--------------|-----------------------------|---------|
| Ikenouye, Teri   |              | teri.ikenouye@state.co.us   |         |
| Freeman, Kris    | 254-717-0435 | kfreeman@31operating.com    |         |
| Thompson, Bud    |              | BLThomps@BLM.gov            |         |
| Boulger, Levin   |              | lboulger@31operating.com    |         |
| Rosenberg, Kelly |              | kelly.rosenberg@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 230249      | WELL | PR     | 03/01/2019  | GW         | 103-07908 | CONTINENTAL 1-8 | PR          |

**General Comment:**

A follow up inspection of documents:  
1) 700404745 dated 12-22-2020.

The following were partially completed:  
1) Past due monthly operations were updated to December 2020.

The following compliance issues are uncompleted:  
1) Provide bradenhead access.  
2) Calibrate gas meter.

**Location**

Overall Good:

**Signs/Marker:**

|                    |                 |       |  |
|--------------------|-----------------|-------|--|
| Type               | WELLHEAD        |       |  |
| Comment:           |                 |       |  |
| Corrective Action: |                 | Date: |  |
| Type               | OTHER           |       |  |
| Comment:           | Meter building. |       |  |
| Corrective Action: |                 | Date: |  |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |
| Type               | PIT      |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                          |  |       |                 |
|--------------------------|--|-------|-----------------|
| Type: Deadman # & Marked | # 1  |       | corrective date |
| Comment:                 |  |       |                 |
| Corrective Action:       |  | Date: |                 |
| Type: Bradenhead         | # 1  |       |                 |
| Comment:                 | Bradenhead access is not present.  |       |                 |
| Corrective Action:       | Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). | Date: | 02/01/2021      |
| Type: Gas Meter Run      | # 1  |       |                 |
| Comment:                 | Most recent meter calibration on 6-17-2019.  |       |                 |
| Corrective Action:       | Calibrate gas metering equipment annually to comply with rule 430.d.(1).                       | Date: | 02/01/2021      |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 230249 Type: WELL API Number: 103-07908 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Most recent reported monthly operations is for December 2020 with production in December 2020. Audible gas flow in meter building.](#)  
[Report past due monthly operations by submitting required Form 7\(s\) to COGCC per rule 413.a.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |

Comment: No significant soil migration, erosion or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Wildlife    Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:    Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402698028    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5438546">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5438546</a> |
| 701500831    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5438543">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5438543</a> |