

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2021

Submitted Date:

05/23/2021

Document Number:

701500832

FIELD INSPECTION FORMLoc ID 315106 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL & GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Boulger, Levin		lboulger@31operating.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230267	WELL	PR	11/08/2000	GW	103-07926	DEPCO 1-5	PR

General Comment:

A follow up inspection of documents:

- 1) 700404747 dated 12-22-2020.

The following were partially completed:

- 1) Past due monthly operations were updated to December 2020.

The following compliance issues are uncompleted:

- 1) Calibrate gas meter.

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Meter building.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead access present.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Most recent meter calibration on 6-17-2019.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	02/01/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	Open Top		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	3 bbl
Other (Type)	

Berms

Inspector Name: Moran, Rick

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 230267 Type: WELL API Number: 103-07926 Status: PR Insp. Status: PR**Producing Well**Comment: [Most recent reported monthly operations is for December 2020 with production in December 2020. Audible gas flow in meter building.](#)[Report past due monthly operations by submitting required Form 7\(s\) to COGCC per rule 413.a.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [No significant soil migration, erosion or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402698029	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5438547
701500833	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5438544