

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/24/2021

Submitted Date:

05/25/2021

Document Number:

701500862

**FIELD INSPECTION FORM**

Loc ID 315054 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10654  
Name of Operator: LASSO OIL & GAS LLC  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Findings:**

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Heil, John		john.heil@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Boulger, Levin		lboulger@31operating.com	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230175	WELL	PR	09/01/2019	GW	103-07834	FEDERAL 3-34	PR

**General Comment:**

- A follow up inspection of documents:
  - 1) 700404765 dated 12-23-2020.
- The following were partially completed:
  - 1) Past due monthly operations were updated to December 2020.
- The following compliance issues are uncompleted:
  - 1) Calibrate gas meter.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Meter building.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Overall Good:

**Spills:**

Type	Area	Volume	
------	------	--------	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:			Date:

**Equipment:**

Type			corrective date
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Gas Meter Run	# 1		
Comment:	Most recent meter calibration on 6-20-2019.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: <u>02/01/2021</u>
Bradenhead	# 1		
Comment:	Bradenhead open to atmosphere.		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 230175 Type: WELL API Number: 103-07834 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Most recent reported monthly operations is for December 2020 with production in December 2020. Audible gas flow in meter building.](#)  
[Report past due monthly operations by submitting required Form 7\(s\) to COGCC per rule 413.a.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: No significant soil migration, erosion or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Wildlife    Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:    Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402700496	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440704">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440704</a>
701500863	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440697">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440697</a>