

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2021

Submitted Date:

06/01/2021

Document Number:

696303288

FIELD INSPECTION FORMLoc ID 317496 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 42950

Name of Operator: INDUSTRIAL GAS SERVICES INC

Address: 4891 INDEPENDENCE ST STE 200

City: WHEATRIDGE State: CO Zip: 80033

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		igsinc@att.net	All Inspections
Allison, Rick		rick.allison@state.co.us	
,		dnr_cogccengineering@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
Dinku, Ted		ted.dinku@state.co.us	
Lindley, Trent		trent.lindley@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238354	WELL	SI	05/01/2016	GW	123-05198	BEHRING 1	SI

General Comment:

This is a Follow-Up Inspection to FIR 696302592 dated 10.26.2020. And a Response Inspection to NOAV Issued 402668945 dated 04.23.2021. Also Response to Warning Letter 402359758 dated 04.02.2020

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	The Unsued Equipment South of Pit has been removed		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	Weeds have been cleared. Prevent future growth. Regular Routine Inspections will be conducted.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: Stained Soils at - Wellhead, Gas Engine, Loadline have been removed

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead NOW appears to be plumbed to surface Refer to Warning Letter #402359758 dated 04.02.2020 for the Bradedhead Test Requirements.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Flowline is in the Process of being Abandoned by Opearator per Rule 1103		
Corrective Action:	Properly abandon flowlines to former pit. Comply w/ Rule 1103. Original Corrective Action date: 03/20/2017. See photos Prior CA remains applicable.		Date: 03/20/2017
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:	Contact Gas Operating Company prior to Return-To-Production for updated Calibration				
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	Gas Engine. Stained Soil has been cleaned up.				
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	FIBERGLASS AST		40.440350,-104.170070	
Comment:	Berms have been Restored					
Corrective Action:					Date:	

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	30 BBLS				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:	Berms have been restored					
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	OTHER	STEEL AST		40.440581,-104.169996	
Comment:	210 BBL Tank will remain. Deemed NOT Visible for Roadway. And NOT Rusted for Mechanical Conditions					
Corrective Action:					Date:	

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	210 BBLS and 500 BBLS				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Berms have been Restored				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected FacilitiesFacility ID: 238354 Type: WELL API Number: 123-05198 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI. Last Produced April 2016. Current MIT 06.26.2019 per Approved Form 21 #1732418

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Bradenhead has been plumbed to surface.
Refer to Warning Letter #402359758 dated 04.02.2020 for the Bradedhead Test
Requirements.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat: 40.440308Long: -104.170424Reference Point: SE

Other: _____

Length: 20Width: 15**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective

Date:

Fencing:Fencing Type: LivestockFencing Condition: AdequateComment: Electric Fence installed around Pit

Corrective

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YES

Comment:

Prior FIR.
 Pit Closure and Soil Remediation is in Process. Soil does not yet Comply with Table 910-1 Concentration Levels. Operator is directed to Submit plan and Timeframe for Compliance with Table 910-1 Concentration Levels.
 **Note spoke with Operator. Soil Test has been completed and is waiting Results. Operator has been in Contact with Rick Allison.

Corrective

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary: On Monday 05/24/2020 at approximately 10:30 hrs. I, Inspector, Erica Petrie, conducted an on-site Inspection at: Operator Name: INDUSTRIAL GAS SERVICES INC. Location Name: BEHRING 1 Location ID: 317496 Location County: Weld County, Colorado While there, I observed: Well - 1: Shut-In Entire battery & equipment is shut-down.</p> <p>This is a Follow-Up Inspection to FIR 696302592 dated 10.26.2020. And a Response Inspection to NOAV Issued 402668945 dated 04.23.2021. Also Response to Warning Letter 402359758 dated 04.02.2020 ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE. Prior Corrective Action dates remain applicable. 3 of 8 - Corrective Actions from prior FIR NOT addressed.</p> <p>1.) Weeds have been removed from Location. Manage & control weeds to prevent future growth. Regular Field Inspections will be conducted to ensure future Compliance. See photos.</p> <p>2.) Unused Equipment (Pipe) at South Side of Pit has been removed.</p> <p>3.) Spill & Stained soil at wellsite. <= 1 Bbl. Stained soil at Pumping Unit Engine House, Wellhead and Crude Oil Tanks Loadout. All Stained Soil has been removed. Material around Wellhead has been worked but impacted soil remains in place. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition to Prevent Future Impact.</p> <p>*4.) Flowlines from Treater to Pit NOT properly abandoned. Refer to Rule 1103 for guidance. Properly abandon flowlines to former pit. Comply w/ Rule 1103. Original Corrective Action date: 03/20/2017. See photos. Operator STILL in process of Abandoning Flowline.</p> <p>5.) Crude oil tanks berm have been fixed. See photos</p> <p>*6.) Crude Oil Tanks. 500 BBLs Bolted Tank is in the Process of being removed from Location. 210 BBLs Tank will remain. Deemed NOT visible from the Road or Rusted for Mechanical Issues. See photos.</p> <p>*7.) Bradenhead is NOW plumbed to surface. Refer to Warning Letter #402359758 dated 04.02.2020 for the Bradenhead Test Requirements.</p> <p>*8.) Pit Closure and Soil Remediation is in Process. Soil does not yet Comply with Table 910-1 Concentration Levels. Operator is directed to Submit plan and Timeframe for Compliance with Table 910-1 Concentration Levels. **Note spoke with Operation. Soil Test has been completed and is waiting Results. Operator has been in Contact with Rick Allison.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petrie	05/25/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303289	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5444361