

Inspection Photos

API: 055-06105

Operator: OXY USA INC

Inspection Date: 5/26/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06105 | Date: 5/26/2021

Inspection Photos



Photo 1. Facing southeast ascending the hill toward the location. There is erosion occurring along the road. BMP's are needed in this area along the road to prevent further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 5/26/2021

Inspection Photos



Photo 2. Facing northwest looking back down the road. There is erosion occurring along the road. BMP's are needed in this area along the road to prevent further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06105 | Date: 5/26/2021

Inspection Photos



Photo 3. Facing northwest at the location. There is various unused equipment stored in this area. Since last year during inspection, the amount of unused equipment has increased in this area and remains in the same position indicating the equipment has not been used.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06105 | Date: 5/26/2021