

Inspection Photos
Operator: Simcoe
API: 067-07854
Date: 5/28/2021



Photo 1. View of project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is mixed with desirable vegetation such as smooth brome, and weeds such as yellow tumbled mustard, Canada thistle, and Scotch thistle.



Photos 3/4. View of Canada thistles (left) and Scotch thistles (right) observed within the project area.



Photos 5. View trucks, trailers, farm equipment, and storage containers parked within the northern project area.



Photos 6. View of metal debris observed within the western interim reclamation area.



Photos 7/8. View of reference area(s), comprised of irrigated grass field (left) and pinyon and juniper woodland (right). As project area is located at the edge of these two reference areas, surface owner will determine whether final reclamation will return the area to native woodland habitat or irrigated crop field.