

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2021

Submitted Date:

05/27/2021

Document Number:

700702814

FIELD INSPECTION FORM

 Loc ID 316301 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 110 W 7TH STREETCity: FORT WORTH State: TX Zip: 76102**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments2 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
Sutton, Derek		derek_sutton@xtoenergy.com	Area foreman
Dooling, Jes	832-624-0810	jessica.dooling@exxonmobil.com	Lead regulatory coordinator
Clark, Erin	405-319-3250	erin.k.clark@exxonmobil.com	Lead regulatory coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261106	WELL	PR	08/01/2017	GW	103-10195	PICEANCE CREEK UNIT T32X-33G	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday at approximately 0900, I, Inspector Scott Ramsey, conducted a routine inspection at XTO T32X-33G, at Location # 316301 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also within BLM stipulations area.

During this inspection the following possible compliance issues were observed:

1. Location and access road show signs of lack of stabilization/compaction.
2. Fill slope on location is eroding/lack of stabilization, sediment migration is choking out vegetation.
3. Lack of battery signage.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:	see stormwater		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lack of battery signage.		
Corrective Action:	Comply with rule 605.e		Date: 07/02/2021
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	# 1		corrective date
Comment:	well head not on plunger lift		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:			Date:

Type: Bradenhead	# 1	
Comment:	Braden heads have a PSI gauge for monitoring.	
Corrective Action:		Date:
Type: Horizontal Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:	210 bbl tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		,
Comment:	210 bbl tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 261106 Type: WELL API Number: 103-10195 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction	Fail			
		Ditches				
		Culverts				
Compaction	Fail					

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also within BLM stipulations area.
 1. Location and access road show signs of lack of stabilization/compaction.
 2. Fill slope on location is eroding/lack of stabilization, sediment migration is choking out vegetation.

Corrective Action: **Install or repair required BMPs**

Date: 07/02/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402703403	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442930
700702820	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442925