

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2021

Submitted Date:

05/27/2021

Document Number:

700702818

**FIELD INSPECTION FORM**Loc ID 316627 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	832-624-0810	jessica.dooling@exxonmobil.com	
clark, Erin	405-319-3250	erin.k.clark@exxonmobil.com	
Sutton, Derek		derek_sutton@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289234	WELL	SI	05/15/2015	GW	103-10991	FEDERAL 2S-95-16-24AP	TA

**General Comment:****COGCC Inspection Report Summary**

On Wednesday at approximately 1300, I, Inspector Scott Ramsey, conducted a routine inspection at XTO Federal 2S-95-16-24AP, at Location # 316627 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also within BLM stipulations area.

During this inspection the following possible compliance issues were observed:

1. Lack of battery signage.
2. Unused equipment (pump jack is disconnected and not in use, and associated equipment with pump jack)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Lack of battery signage.		
Corrective Action:	Comply with rule 605.e	Date:	07/02/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (pump jack is disconnected and not in use, and associated equipment with pump jack)		
Corrective Action:	remove unused equipment		Date: 08/27/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Pump Jack	# 1		corrective date
Comment:	see unused equipment		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	water transfer pump		
Corrective Action:			Date:

Type: Bradenhead	# 1	
Comment:	Braden heads have a PSI gauge for monitoring.	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	well head is T/A	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		,
Comment:	LOTO				
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		,
Comment:	LOTO				
Corrective Action:			Date:		

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 289234 Type: WELL API Number: 103-10991 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last MIT was done 6/28/2019

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Culverts				
		Ditches				
Berms						

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also within BLM stipulations area. During this inspection the following possible compliance issues were

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	414372	1630570	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402703411	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442949">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442949</a>
700702822	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442928">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442928</a>