

Inspection Photos
Location Name: MV 9-32 PAD
Location ID: 335087 & Spill/Release ID: 479989
Inspection Date: May 25, 2021



Location sign.



Excavation located northwest of the tank battery.



Inspection Photos

Location Name: MV 9-32 PAD

Location ID: 335087 & Spill/Release ID: 479989

Inspection Date: May 25, 2021



Excavation northwest of the tank battery. Note the tank battery is in disrepair but still in use.



Stockpiles of potentially impacted material located adjacent to the excavation sidewalls.

Inspection Photos

Location Name: MV 9-32 PAD

Location ID: 335087 & Spill/Release ID: 479989

Inspection Date: May 25, 2021



Newly installed 200 bbl Steel AST condensate tank.



Newly installed 200 bbl Steel AST condensate tank, note the newly installed flowline that is attached to the Steel AST and the secondary containment structure in disrepair (green oval).



Inspection Photos

Location Name: MV 9-32 PAD

Location ID: 335087 & Spill/Release ID: 479989

Inspection Date: May 25, 2021



Wells associated with the MV 9-32 PAD Location. Note all wells appeared to be producing at time of inspection and have a PR status in the COGIS database.



View of the MV 9-32 PAD PAD from the pad where the associated wells are located.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: MV 9-32 PAD

Location ID: 335087 & Spill/Release ID: 479989

Inspection Date: May 25, 2021



Starkey Gulch up-gradient of Spill/Release ID 479989.



Starkey Gulch down-gradient of Spill/Release ID 479989.

