

Inspection Photos
UPRR 43 PAN AM G Consolidation #2
Remediation Project #16131/Spill ID 478086 (CL)



Photo 1 – Spill area with open excavation.



**Photo 2 – Open excavation with groundwater.
Impacts appear to remain in situ.**

Inspection Photos
UPRR 43 PAN AM G Consolidation #2
Remediation Project #16131/Spill ID 478086 (CL)



Photo 3 – Open excavation. Hydrocarbon sheen observed on groundwater.



Photo 4 – Soils previously stored on location have been removed. Trash removed from location.