

Inspection Photos

API: 055-06309

Operator: ALTA MESA SERVICES LP

Inspection Date: 5/26/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 5/26/2021

Inspection Photos



Photo 1. Facing north toward the location. The access road has not been reclaimed. The cattle guard, gates, and fence remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 5/26/2021

Inspection Photos



Photo 2. Facing northwest toward the location. This portion of the location has not been recontoured and reclaimed. There are undesirable and noxious weeds growing throughout the location which have not been controlled. Red arrow points to Scotch thistle and Common mullein.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 5/26/2021

Inspection Photos



Photo 3. Facing north toward where the gravel pad remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 5/26/2021

Inspection Photos



Photo 4. Facing northwest at the location. The reclaimed area consists of mostly undesirable weeds due to lack weed management.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 5/26/2021

Inspection Photos



Photo 5. There is undesirable and noxious weeds throughout the location which have not been controlled. Photo shows various weed including Scotch thistle, Cheat grass, and Tansy mustard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 5/26/2021

Inspection Photos



Photo 6. Facing southwest at the location. There are dead trees that were planted and have not been removed and replaced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 5/26/2021

Inspection Photos



Photo 7. Facing southeast at the location. This portion of the location was not reclaimed and gravel remained on this flat portion. There are undesirable weeds throughout this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 5/26/2021

Inspection Photos



Photo 8. There are undesirable weed debris that has accumulated along the perimeter fence line.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 5/26/2021

Inspection Photos



Photo 9. Facing southwest at the east side of the location. This area of the location has not been recontoured and reclaimed and gravel remains within this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 5/26/2021

Inspection Photos



Photo 10. Facing east toward the surrounding undisturbed reference area which consists of Pinyon Juniper woodland and native grassland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06309 | Date: 5/26/2021