

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2021

Submitted Date:

06/05/2021

Document Number:

696104621

FIELD INSPECTION FORM

Loc ID 451073 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

30 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451067	WELL	PR	05/27/2019	OW	123-44964	Wells Ranch BB09-674	PR
451068	WELL	PR	11/01/2020	OW	123-44965	Wells Ranch State BB09-683	PR
451069	WELL	PR	04/11/2018	OW	123-44966	Wells Ranch BB11-674	PR
451070	WELL	PR	05/27/2019	OW	123-44967	Wells Ranch BB09-665	PR
451071	WELL	PR	04/15/2018	OW	123-44968	Wells Ranch BB11-667	PR
451072	WELL	PR	04/01/2018	OW	123-44969	Wells Ranch BB11-682	PR

General Comment:

This is a WELL / BATTERY inspection.
Well(s): 6: Producing | PR.
Battery: Active.

Centralized Battery serves 3 Location IDs
(451073, 451045, 451060).
(Well(s): 18: Producing | PR).

Location

Lease Road:			
	Type Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type WELLHEAD		
Comment:	6: Wellsites.		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
	Type CONTAINERS		
Comment:	Methanol, Corrosion Inhibitor, Motor oil, Coolant.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type OTHER		
Comment:	Gas lift manifolds. Iron pipe.		
Corrective Action:			Date:
	Type TANK BATTERY		
Comment:	Partial Iron Pipe corner fencing protects various on site equipment.		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:	6: Wellsites. Iron panel.		
Corrective Action:			Date:
	Type LOCATION		

Comment: Barbed wire.		Date:
Corrective Action:		Date:
Equipment:		corrective date
Type: Compressor	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 2	
Comment: Gas generators supply electricity to power bank.		
Corrective Action:		Date:
Type: Other	# 1	
Comment: Electric power bank.		
Corrective Action:		Date:
Type: LACT	# 1	
Comment: w/ crude oil transfer line.		
Corrective Action:		Date:
Type: Emission Control Device	# 2	
Comment: 1: Crude oil flow-thru bulk tank vapor line combustor. Controls crude oil flow-thru bulk tank vapors. Pilots: ON.		
1: Separators vapor line combustor. Controls separators vapors. Pilots: ON.		
Corrective Action:		Date:
Type: Plunger Lift	#	
Comment: 6: Wellsites.		
Corrective Action:		Date:
Type: Vertical Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment: Bulk flow-thru crude oil tank.		
Corrective Action:		Date:
Type: Gathering Line	# 1	
Comment: Produced H2O transfer line.		
Corrective Action:		Date:
Type: Bradenhead	#	
Comment: 6: Wellsites. Appears plumbed to surface.		
Corrective Action:		Date:
Type: Pig Station	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 20	

Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 16		
Comment:	<p>At wellsites: 2: Corrosion Inhibitor pumps, tanks w/ drip containment. Placarded. 3: Methanol pumps, tanks w/ drip containment. Placarded.</p> <p>At Battery: 2: ECD scrubbers. 2: Compressor scrubbers. 4: Methanol pumps, tanks w/ drip containment. Placarded. 1: Methanol bulk tank w/ drip containment. Placarded. 1: Motor oil tank w/ drip containment. Placarded. 1: Coolant tank w/ drip containment. Placarded.</p>		
Corrective Action:			Date:
Type: Gas Meter Run	# 9		
Comment:	<p>1: Master Sales: Calibration card indicates calibration within last year. Last calibration: 05/21/2021. Active w/ production.</p> <p>2: Sales allocation meters: Calibration card indicates calibration within last year. Last calibration: 05/21/2021. Active w/ production.</p> <p>6: Gas lift allocation meters: Calibration card indicates calibration within last year. Last calibration: 08/27/2020. Active.</p>		
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 18		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery serves 3 Location IDs (451073, 451045, 451060).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.416167,-104.411952
Comment: Maintenance tank.					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLs	CONCRETE SUMP/VAULT		,
Comment: For LACT.					
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)	H2O drip				
Other (Capacity)	12 Bbls.				
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	2	<50 BBLs	CONCRETE SUMP/VAULT		,
Comment: For Compressor & Compressor scrubbers.					
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)	H2O drip				
Other (Capacity)	7 Bbls.				
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities			
Facility ID: <u>451067</u>	Type: <u>WELL</u>	API Number: <u>123-44964</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: Producing PR.			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: <u>02/12/2021</u>	Annual Brhd Completed? <u>Yes</u>		
Last Brhd Test Results	Initial Surf Csg Pressure: <u>64</u>	Fluid Type: <u>NONE</u>	
	End Surf Csg Pressure: <u>0</u>		
Comment:			
Corrective Action:		Date:	
Facility ID: <u>451068</u>	Type: <u>WELL</u>	API Number: <u>123-44965</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: Producing PR.			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: <u>12/04/2020</u>	Annual Brhd Completed? <u>Yes</u>		
Last Brhd Test Results	Initial Surf Csg Pressure: <u>18</u>	Fluid Type: <u>NONE</u>	
	End Surf Csg Pressure: <u>0</u>		
Comment:			
Corrective Action:		Date:	
Facility ID: <u>451069</u>	Type: <u>WELL</u>	API Number: <u>123-44966</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: Producing PR.			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: <u>01/05/2021</u>	Annual Brhd Completed? <u>Yes</u>		
Last Brhd Test Results	Initial Surf Csg Pressure: <u>28</u>	Fluid Type: <u>NONE</u>	
	End Surf Csg Pressure: <u>0</u>		
Comment:			
Corrective Action:		Date:	
Facility ID: <u>451070</u>	Type: <u>WELL</u>	API Number: <u>123-44967</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: Producing PR.			
Corrective Action:		Date:	

BradenHead

Date of Last Brhd Test: 04/26/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 68 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 451071 Type: WELL API Number: 123-44968 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/04/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Facility ID: 451072 Type: WELL API Number: 123-44969 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/01/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 06/04/2021 at approximately 14:51 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: BB11-04 /Pad Location ID: 451073 Well Name(s): Wells Ranch BB09-674, Wells Ranch State BB09-683, Wells Ranch BB11-674, Wells Ranch BB09-665, Wells Ranch BB11-667, Wells Ranch BB11-682. API: 05-123-44964, 05-123-44965, 05-123-44966, 05-123-44967, 05-123-44968, 05-123-44969. Location County: Weld County, Colorado Weather: Sunny, dry.</p> <p>While there, I observed: Well(s): 6: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 3 Location IDs (451073, 451045, 451060). (Well(s): 18: Producing PR).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/05/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104622	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5448241