

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/02/2021

Submitted Date:

06/07/2021

Document Number:

688800020

FIELD INSPECTION FORM

Loc ID 312042 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10363
Name of Operator: SCHUTZ* RICHARD E
Address: PO BOX 66
City: CHROMO State: CO Zip: 81128

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schutz, Dick	(970) 264-4436	schutzre@yahoo.com	All Schutz Inspections
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Schutz, Sherry		schutzsherry@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204998	WELL	PR	12/01/2020	OW	007-05038	FITZHUGH 6	EI

General Comment:

On June 2, 2021 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Fitzhugh #6, 7, and 15 as they relate to REM #10228. For the most recent field inspection report of this facility, please refer to document #688800790.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to stock panel enclosure around well head.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign mounted to stairway for AST, placard on tank.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	Truck Loadout	<= 1 bbl	
Comment:	Drip pan beneath load out valve on AST is full and overflowing.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: <u>07/07/2021</u>
Crude Oil	Pump Jack	<= 1 bbl	
Comment:	Well head and surrounding soil is wet and stained with oil.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: <u>07/07/2021</u>
In Containment: No			
Comment:			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel enclosure around Fitzhugh #6 well head.		
Corrective Action:		Date:	
Equipment:			
Type: Prime Mover	# 1		corrective date
Comment:	Electric motor.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		37.050851,-106.845992
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Wells Served By Facilities Above

API Number
007-05038

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 204998 Type: WELL API Number: 007-05038 Status: PR Insp. Status: EI

Environmental

Spill/Remediation:

Comment: REM #10228 has an active status in the COGIS database.

Corrective Action: Per Rule 913.e(2), the operator will submit a Supplemental Form 27, with a detailed project summary and status, for all existing remediation projects approved prior to January 15, 2021 by April 15, 2021.

Date: 04/15/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	In Process	Drip pan beneath load out valve is full of oil.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On June 2, 2021 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Fitzhugh #6, 7, and 15 as they relate to REM #10228. For the most recent field inspection report of this facility, please refer to document #688800790. Land farmed material from the excavation near the PA Fitzhugh #7 is still being treated in two cells near the barn. The Fitzhugh #6 well head and surrounding area are wet and stained with oil. The drip pan beneath the load out valve on the AST is full and the contents are spilling over</p>	hughesjo	06/07/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800022	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5449098