

Inspection Photos

API: 073-06501

Operator: GRAND MESA OPERATING CO

Inspection Date: 6/2/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06501 | Date: 6/2/2021

Inspection Photos



Photo 1. Facing north long the access road toward the abandoned tank battery facility which was reclaimed and fenced. The disturbed area adjacent to the fence appears to need additional reclamation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06501 | Date: 6/2/2021

Inspection Photos



Photo 2. The vegetation inside the fenced area consists mostly of undesirable weeds. Weed control will need to be performed and additional reseeding may be needed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06501 | Date: 6/2/2021

Inspection Photos



Photo 3. Facing northeast along the access road. Additional reclamation is needed along this area of the access road. A pre-existing road appeared to travel thru the location however the location has been fenced off.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06501 | Date: 6/2/2021

Inspection Photos



Photo 4. Facing northeast at the location. It does not appear revegetation is progressing in areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06501 | Date: 6/2/2021

Inspection Photos



Photo 5. Facing south at the location. It does not appear revegetation is progressing in areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06501 | Date: 6/2/2021

Inspection Photos



Photo 6. View of ground cover shows crimped straw. With the abundant spring moisture areas of the location should be establishing vegetation. Additional reseeding and weed control will need to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06501 | Date: 6/2/2021

Inspection Photos



Photo 7. Facing southwest at the location. It does not appear revegetation is progressing in areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06501 | Date: 6/2/2021

Inspection Photos



Photo 8. It was observed in the photos that there is potential noxious weeds (Russian knapweed). The location needs to be evaluated for both undesirable and noxious weed control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06501 | Date: 6/2/2021

Inspection Photos



Photo 9. Facing west toward the undisturbed surrounding rangeland which consists of Blue grama, Sand dropseed among other native vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06501 | Date: 6/2/2021