

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Pit content label is weathered & Capacity label is missing. Both need replaced. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	07/01/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Trash in multiple spots needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606	Date:	07/01/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbwire		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.389200,-104.371800

Comment:	Date:
Corrective Action:	Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: Weathered Berms need to be repaired. See attached photos.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: <u>07/01/2021</u>

Venting:

Yes/No	NO		Date:
Comment:			
Corrective Action:			Date:

Flaring:

Type		Date:
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 244294 Type: WELL API Number: 123-12088 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: T/A

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/02/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 6/8/21 at approximately 0900hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Farr 2-19 of Bonanza Creek Energy, at Location ID # 322807 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Pit content label is weathered & Capacity label is missing. Install sign to comply with Rule 605.g. With a corrective action date of 7/1/21 Trash in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 7/1/21 Weathered Berms need to be repaired. Repair or install berms or other secondary containment devices per Rule 603.o. With a corrective action date of 7/1/21 Gas meter appears to not have an annual calibration. Calibrate before returning to production. See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	06/08/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103869	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5449450