

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2021

Submitted Date:

06/03/2021

Document Number:

697601372

FIELD INSPECTION FORMLoc ID 476325 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Knop, Max	303-825-4822	MKnop@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478861	SPILL OR RELEASE	AC	12/18/2020		-	Premium Turkey Farm PW Vault	AC

General Comment:

Environmental inspection of spill 478861 and associated site investigation and remediation project 16538.

Past corrective actions still to be completed unless acknowledged as completed with FIRRs.

Operator staff and contractors on site with active excavation underway.

Operator representative indicated that impacted material was being hauled away as excavation was done.

Small amount of impacted soils piled near excavation on site.

Three trucks present to haul away materials.

Operator representative indicated excavation was closed off at end of days activities as only partially fenced at time of inspection so that heavy equipment access was possible.

Inspected Facilities									
Facility ID:	478861	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	AC

--

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 250

Comment: full lateral and vertical extent of impacts may not have been determined

Corrective Action: Comply with 912.a(1) and 912.b(2) and rule 913.b(2) which requires that the full horizontal and vertical extent be determined by conducting sampling and analysis of soils and groundwater (if present) and groundwater may be shallow at the site. corrective action date same as in previous inspections

Date: 05/20/2021

Reportable: YES

GPS: Lat Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location: Comment:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402707558	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5446474
697601373	open excavation, backhoe with impacted soils under backhoe arm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5446472
697601374	open excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5446473