

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2021

Submitted Date:

06/03/2021

Document Number:

701500910

FIELD INSPECTION FORM

Loc ID 396917 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 27900
Name of Operator: EQUITY OIL CO
Address: 1700 BROADWAY STE 2300
City: DENVER State: CO Zip: 80290-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Swain, Scott		scott.swain@whiting.com	
CO, Western	303-876-7091	whitingwesternco@whiting.com	Western slope inspections
Katz, Aaron		aaron.katz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228553	WELL	PA	10/01/1961	DA	103-05446	EMERALD C 134	PA

General Comment:

A routine inspection identified the following compliance issues:
1) An incorrect API number & coordinate are on the plugged well name plate.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	The well name plate has the API # and coordinate of another well. The correct API is 103-05446. Coordinate 40.08776897 and 108.89438438.		
Corrective Action:	Correct the API # and coordinate before covering with dirt.	Date:	07/03/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 228553 Type: WELL API Number: 103-05446 Status: PA Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Diamondback

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Gravel of 36 yards from tagged TD of 1488' to 476'. Cement of 90 sx from 470' to 343'. An additional section of gravel followed by cement was added. Name plate welded on top of the casing. Name plate left exposed for soil sampling & to correct the name plate.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						Vegetation.

Comment: No significant soil migration, erosion or soil movement on location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402707529	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5446452
701500911	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5446445