

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2021

Submitted Date:

06/07/2021

Document Number:

688800016

FIELD INSPECTION FORMLoc ID 320864 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 900

Name of Operator: ALAMOSA DRILLING INC

Address: 8150 N. CENTRAL EXPY - STE 750

City: DALLAS State: TX Zip: 75205-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Mercer, Lauren		Lauren.Mercer@coag.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205262	WELL	PR	07/01/2020	OW	007-06141	NIELSEN 5	EI

General Comment:

On June 2, 2021 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Alamosa Drilling Nielson #5. For the most recent environmental field inspection report of this facility, please refer to document #688800883.

Location			
Lease Road:			
Type	Access		
comment:	Well head accessed by walking through agricultural field.		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to perimeter fencing for pump jack. Well head sign is not in compliance with Rule 605.d.		
Corrective Action:	Install sign to comply with Rule 605.d(1).		Date: 05/14/2021
Type	BATTERY		
Comment:	Tank battery sign is not compliant with Rule 605.e(2).		
Corrective Action:	Install sign to comply with Rule 605.e(2).		Date: 05/14/2021
Type	TANK LABELS/PLACARDS		
Comment:	AST is labeled with contents, capacity, and has NFPA placard.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Location signs do not have emergency services contact listed on them as required by Rule 605.d.		
Corrective Action:	Install sign to comply with Rule 605.		Date: 05/14/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	The well head and surrounding area is wet and stained with oil.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 04/15/2021
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Post and wire perimeter fencing around pump jack and well head.		
Corrective Action:			Date:
Equipment:			
Type: Flow Line	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Type: Prime Mover	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		STEEL AST		37.017703,-106.876876
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Secondary containment berm does not appear to have adequate capacity.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			
			Date:	05/14/2021

Wells Served By Facilities Above**AirsID**

API Number
007-06141

API Number	AirsID
------------	--------

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	205262	Type:	WELL	API Number:	007-06141	Status:	PR	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On June 2, 2021 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Alamosa Drilling Nielson #5. For the most recent environmental field inspection report of this facility, please refer to document #688800883. The well head and surrounding area are wet and stained with oil. Soil berm has been pushed up near well head.	hughesjo	06/07/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402710336	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5449015
688800018	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5449001