

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE-67S95W /20SESE

Location ID: 334996



Photo #4063 from entrance to location.



Photo #4064 from entrance to location.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE-67S95W /20SESE

Location ID: 334996



Photo #4065 from entrance to location.



Photo #4066 No battery sign located at the tanks battery.





## Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE-67S95W /20SESE

Location ID: 334996



**Photo #4067 Multiple flow line heating insulation open ended and not capped.**



**Photo #4068 Location lacks stabilization.**




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE-67S95W /20SESE

Location ID: 334996



**Photo #4069 Location lacks stabilization.**



**Photo #4070 No form of tracking control located at the entrance to location.**