

Inspection Photos

API: 061-06590

Operator: OXY USA INC

Inspection Date: 6/9/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06590 | Date: 6/9/2021

Inspection Photos



Photo 1. Facing southeast along the former access road. Vegetation has not re-established in this area and there s erosion. Location is shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06590 | Date: 6/9/2021

Inspection Photos



Photo 2. Facing southeast toward the location. This area is not stabilized and there are signs of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06590 | Date: 6/9/2021

Inspection Photos



Photo 3. Facing southwest at the location. The fill slope has not been recontoured. There is no vegetation growth along this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06590 | Date: 6/9/2021

Inspection Photos



Photo 4. Facing west at the location. There is no vegetation observed in the bare areas. With adequate spring moisture, there should be more germination in these areas were seeded. There may be soil issues preventing vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06590 | Date: 6/9/2021

Inspection Photos



Photo 5. Facing northwest at the location. There is no vegetation observed in this bare area approximately 120'x120'. With adequate spring moisture, there should be more germination in this area if it was seeded. There may be soil issues preventing vegetation establishment.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06590 | Date: 6/9/2021

Inspection Photos



Photo 6. Facing southeast at the location. There is no vegetation observed in this bare area approximately 120'x120'. With adequate spring moisture, there should be more germination in this area as it was seeded. There may be soil issues preventing vegetation establishment. Red arrow points to fill slope area shown in photo 3.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06590 | Date: 6/9/2021

Inspection Photos



Photo 7. Facing northeast along the cut slope. Soil has been replaced along the cut slope. There are some signs of erosion and soils are not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06590 | Date: 6/9/2021

Inspection Photos



Photo 8. Facing north at the cut slope. Soil has been replaced along the cut slope. There is some signs of erosion and soils are not stabilized (Red arrow).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06590 | Date: 6/9/2021

Inspection Photos



Photo 9. Facing northwest at the at the eastern corner of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06590 | Date: 6/9/2021

Inspection Photos



Photo 10. Facing east toward the surrounding undisturbed rangeland consisting of Blue grama, Sand dropseed among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06590 | Date: 6/9/2021