

Inspection Photos

Location Name: August Gittlein #1 and Spindle Consolidation Battery #6

Location ID: 317646



Photo 1 TNK BTRY sign

Photo 2 Recirc pump. Stained soil and mechanical issues.

Inspection Photos

Location Name: August Gittlein #1 and Spindle Consolidation Battery #6

Location ID: 317646



Photo 3 TNK BTRY



Photo 4 Labels and placards faded not readable.

Inspection Photos

Location Name: August Gittlein #1 and Spindle Consolidation Battery #6

Location ID: 317646



Photo 5 Meter calibration card out of date



Photo 6 Produced water tank not placards or labels.

Inspection Photos

Location Name: August Gittlein #1 and Spindle Consolidation Battery #6

Location ID: 317646



Photo 7 Loc pic



Photo 8 August Gittlein # 1 PU

Inspection Photos

Location Name: August Gittlein #1 and Spindle Consolidation Battery #6

Location ID: 317646



Photo 9 Stained soil around well head.



Photo 10 electric panel. Breaker in the on position.