

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402707560

Date Received:

06/14/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

SG Interests

inspection@sginterests.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202526

Inspection Date: 03/31/2021

FIR Submit Date: 04/02/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 429333

Location Name: Federal 12-89-7 Number: 1 County: _____

Qtrqr: NESE Sec: 7 Twp: 12S Range: 89W Meridian: 6

Latitude: 39.025470 Longitude: -107.371390

FACILITY - API Number: 05-051-00 Facility ID: 429333

Facility Name: Federal 12-89-7 Number: 1

Qtrqr: NESE Sec: 7 Twp: 12S Range: 89W Meridian: 6

Latitude: 39.025470 Longitude: -107.371390

CORRECTIVE ACTIONS:

1 ☒ CA# 147984

Corrective Action: Original Corrective Action has not been addressed in its entirety and remains applicable.

Date: 06/18/2019

Comply with Rule 1002.f. Stormwater and erosion controls need to be installed to stabilize erosion on the Location. Cracking in berms needs to be monitored and stabilization measures employed if cracks deepen or slipping occurs. Stormwater controls need to be installed using good engineering practices such as those described in CDOT manuals for stormwater and erosion control.

Response: CA COMPLETED

Date of Completion: 05/19/2021

Operator Comment: As mentioned in previous FIRRs, monitoring of the berms was implemented immediately following the original corrective action in 2019. In SG's observation, the cracks did not deepen and slipping has not occurred. However, the new COGCC inspector decided the corrective action has not been met. Therefore, SG conducted additional measures to fix the cracks (see photos). Outlet protection has been added to the off-pad stormwater settling ponds (see photos). Additional stabilization measures are planned to be implemented as well.

COGCC Decision: Approved

COGCC Representative: Approved per FIR #696202830. Additional worked observed to repair cracking and stabilization issues.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Eric Sanford Signed: _____

Title: Land Date: 6/14/2021 10:18:57 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402707560	FIR RESOLUTION SUBMITTED
402707696	Cracks Fixed
402707697	Cracks Fixed
402717054	Cracks Fixed
402717075	Outlet Protection
402717077	Outlet Protection

Total Attach: 6 Files