

**Inspection Photos**  
**Location Name: Lilli Unit 8-1**  
**Location ID: 326969**



**Photo 1 – TA Wellhead**



**Photo 2 – Stained Soil where Gas Engine was removed**