

Inspection Photos  
Location Name: Elkhorn Company B 6  
Location ID: 327714



Photo 1 WH sign



Photo 2 WH

**Inspection Photos**  
**Location Name: Elkhorn Company B 6**  
**Location ID: 327714**




**Photo 3 ancillary equipment**



**Photo 4 pumpjack**

**Inspection Photos**  
**Location Name: Elkhorn Company B 6**  
**Location ID: 327714**



**Photo 5 weeds growing around location ROW & Deadman anchors.**



**Photo 6 weeds growing around location ROW & Deadman anchors.**



**Inspection Photos**  
**Location Name: Elkhorn Company B 6**  
**Location ID: 327714**



**Photo 7 weeds growing around location ROW & Deadman anchors.**



**Photo 8 weeds growing around location ROW & Deadman anchors.**

Inspection Photos  
Location Name: Elkhorn Company B 6  
Location ID: 327714





Photo 9 TB sign

Photo 10 TB



**Inspection Photos**  
**Location Name: Elkhorn Company B 6**  
**Location ID: 327714**



**Photo 11 stained soil by TB valve**



**Photo 12 stained soil by TB valve**

**Inspection Photos**  
**Location Name: Elkhorn Company B 6**  
**Location ID: 327714**



**Photo 13 stained soil by TB valve**



**Photo 14 stained soil by TB valve**



**Inspection Photos**  
**Location Name: Elkhorn Company B 6**  
**Location ID: 327714**



**Photo 15 Gas Meter Run**



**Photo 16 Flow line manifold**



**Inspection Photos**  
**Location Name: Elkhorn Company B 6**  
**Location ID: 327714**



**Photo 17 Stained soil by flow line manifold**



**Photo 18 Stained soil by flow line manifold**

**Inspection Photos**  
**Location Name: Elkhorn Company B 6**  
**Location ID: 327714**



**Photo 17 Stained soil by flow line manifold**



**Photo 18 Horizontal Heated Separator**



**Inspection Photos**  
**Location Name: Elkhorn Company B 6**  
**Location ID: 327714**



**Photo 19 ECD**