

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2021

Submitted Date:

06/15/2021

Document Number:

696303351

FIELD INSPECTION FORM

Loc ID 431634 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10503
Name of Operator: RED HAWK PETROLEUM LLC
Address: 575 N DAIRY ASHFORD STE 201
City: HOUSTON State: TX Zip: 77079

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
Boyd, William		wboyd@pedevco.com	All Inspections
Shepard, DeAnn		dshepard@pedevco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431633	WELL	PR	02/01/2018	OW	123-36703	Buchner 2-2H	PR

General Comment:

[Follow-Up Inspection to FIR 696303128 dated 04.13.2021 and in response to FIRR 402668955 date 04.23.2021](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Concrete Vault missing Tank Labels - NFPA, Content, and Capacity. See photos. STILL NOT addressed Corrective Action Date remains the same.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 03/08/2021

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil and Mechanical Conditions STILL REMAIN at Gearbox, Gas Engine and Flare, see photos. Corrective Action Date remains the same		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition For localized stained soils or oily waste - Properly dispose of oily waste per Rule 608.e.		Date: 12/23/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Flare	# 1			
Comment:				
Corrective Action:				Date:
Type: Vertical Heater Treater	# 1			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface			
Corrective Action:				Date:
Type: Vertical Separator	# 1			

Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		40.332000,-104.067010
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	Field Flare	
------	-------------	--

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 431633 Type: WELL API Number: 123-36703 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On Thursday 06/10/2021 at approximately 13:42, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Red Hawk Petroleum LLC , Buchner 2-2H, Location #431634 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Stained Soil STILL Remain at Gearbox, Gas Engine house, see photos. Original Corrective Action Date still remains at 12.23.2020</p> <p>Concrete Vault missing Tank Labels - NFPA, Content, and Capacity. See photos. Corrective Action Date remains the same at 03.08.2021</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p>	petrie	06/14/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402718980	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5455459
696303352	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5455451