



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s)		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/16/2021

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: Chainlink

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Equipment:**

	Type: Plunger Lift	# 1			corrective date
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 1				
Comment:	Appears to be plumbed to surface.				
Corrective Action:					Date:

**Venting:**

Yes/No NO

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flaring:**

Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 271045 Type: WELL API Number: 123-21990 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">Wellhead sign missing needs to be replaced rule 605.d.</a>	sernaa	06/16/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402721137	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5457401">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5457401</a>
698703275	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5457391">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5457391</a>