

# Inspection Photos

API: 009-06081

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 6/21/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 009-06081 | Date: 6/21/2021

## Inspection Photos



**Photo 1.** Facing east toward the location..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06081 | Date: 6/21/2021

## Inspection Photos



**Photo 2.** The tank is marked as not in use and labeled Produced Water. Next photo shows oily fluids inside the tank which apparently the tank is in use. Secondary containment is inadequate to contain 150% of the volume of the tank.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06081 | Date: 6/21/2021



## Inspection Photos



**Photo 3.** View of oil fluids inside the tank. Tank is labeled Produced Water which is not accurately labeled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06081 | Date: 6/21/2021

## Inspection Photos



**Photo 4.** There is a pipe riser shown at red arrow with no LOTO.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06081 | Date: 6/21/2021



## Inspection Photos



**Photo 5.** The well sign does not comply with 605. Incorrect Operator Emergency number and missing information. Name and lettering was updated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06081 | Date: 6/21/2021