

Inspection Photos

API# 009-06189

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 6/21/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06189 | Date: 6/21/2021

Inspection Photos



Photo 1. Facing west toward the PW tank and meter shed located adjacent to CR-49 and 575' east of the well. No operator sign is visible from the county road but a sign was observed on backside of tank. Meter shed still appears to be unstable and there is no berm around the tank. Corrective actions were not completed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06189 | Date: 6/21/2021

Inspection Photos



Photo 2. Sign is posted on the meter shed but is faded and not legible.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/21/2021

Inspection Photos



Photo 3. The meter shed is not maintained and remains unstable. Erosion has occurred underneath the meter shed which is a safety concern. Wood blocks are ready to fall over shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/21/2021

Inspection Photos



Photo 4. Corrective actions of the previous inspection were not performed. There is no berm around the 200 bbls tank. There is unused equipment at the location (red arrow). There is erosion occurring around the tank area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/21/2021

Inspection Photos



Photo 5. The tank sign and NFPA label are installed on backside of the tank which is not readily visible from the front side along the county road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/21/2021

Inspection Photos



Photo 6. Facing east toward the well. A sign has been posted but is faded and not legible.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/21/2021

Inspection Photos



Photo 7. The gate is lying on the ground and the fence around the well is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/21/2021

Inspection Photos



Photo 8. The metal panel debris has been removed but there is vegetative debris in the pumpjack which is a fire hazard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06189 | Date: 6/21/2021