

Inspection Photos

API: 009-06341

Operator: SCHREIDER & COMPANY

Inspection Date: 6/21/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing toward the associated facility along CR 55.5 approximately 900' southeast of the Hume 1-20 abandoned well site. All equipment at the associated facility needs to be removed and disturbance reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06341 | Date: 6/21/2021

Inspection Photos



Photo 2. There is a solidified substance in the tank and the netting is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06341 | Date: 6/21/2021

Inspection Photos



Photo 3. All equipment needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06341 | Date: 6/21/2021

Inspection Photos



Photo 4. Sign posted at the facility is listed as the Hume 1-20 which the well was plugged and abandoned in 2005. All equipment should've been removed within 3 months of abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06341 | Date: 6/21/2021

Inspection Photos



Photo 5. Facing north at the plugged and abandoned wellsite. All equipment has been removed at the well site and the vegetation has re-established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06341 | Date: 6/21/2021

Inspection Photos



Photo 6. Facing south at the plugged and abandoned wellsite. All equipment has been removed at the well site and the vegetation has re-established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06341 | Date: 6/21/2021