

Inspection Photos

API: 009-06551

Operator: LORENTZ OIL & GAS

Inspection Date: 6/21/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06551 | Date: 6/21/2021

Inspection Photos



Photo 1. Facing east along the former access road. Vegetation has not re-established along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06551 | Date: 6/21/2021

Inspection Photos



Photo 2. Facing northeast toward the location which has a perimeter fence. Vegetation has re-established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06551 | Date: 6/21/2021

Inspection Photos



Photo 3. There is an area approximately 120'x50' with no vegetation growth. Soil issues may be impacting vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06551 | Date: 6/21/2021