

# Inspection Photos

API: 009-06539

Operator: SANDLIN OIL CORP

Inspection Date: 6/21/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06539 | Date: 6/21/2021

## Inspection Photos



**Photo 1.** Facing east at former well site. The crop has not re-established in the area shown in photo. There is possible soil issues preventing crop establishment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06539 | Date: 6/21/2021

## Inspection Photos



**Photo 2.** Facing back west at former well site. The crop has not re-established in the area shown in photo. There is possible soil issues preventing crop establishment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06539 | Date: 6/21/2021

## Inspection Photos



**Photo 3.** Facing north toward the surround crop vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06539 | Date: 6/21/2021