

Inspection Photos

API: 009-06581

Operator: ENERGY ALLIANCE COMPANY

Inspection Date: 6/21/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06581 | Date: 6/21/2021

Inspection Photos



Photo 1. Facing south at the former well site. The crop has not re-established in the area shown in photo. There is possible soil issues preventing crop establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06581 | Date: 6/21/2021

Inspection Photos




Photo 2. Facing back north at the former well site. The crop has not re-established in the area shown in photo. There is possible soil issues preventing crop establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06581 | Date: 6/21/2021

Inspection Photos



Photo 3. Facing east at the former well site. The crop has not re-established in the area shown in photo. There is possible soil issues preventing crop establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06581 | Date: 6/21/2021

Inspection Photos



Photo 4. Facing north toward the surrounding uniform crop cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06581 | Date: 6/21/2021