

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/08/2021

Submitted Date:

06/23/2021

Document Number:

689805930

FIELD INSPECTION FORM
 Loc ID 312987 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 33825

Name of Operator: GEOTECH PRODUCTION INC

Address: 7844 S ESPANA WAY

City: AURORA State: CO Zip: 80016-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|----------------|-----------------|---------|
| henderson, ralph | (303) 690-0921 | hap7844@aol.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 223186 | WELL | PR | 12/01/2017 | GW | 081-06548 | SPETTER 5-8 | PR |

General Comment:

Routine FIU inspection. Compliance issues observed:

- gas meter not calibrated annually
- no label on tank
- no secondary containment on tank
- no bradenhead access apparent
- no battery sign

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--|-------|------------|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 07/23/2021 |

Emergency Contact Number:

| | | |
|--------------------|--------------|-------------|
| Comment: | 303-888-7373 | |
| Corrective Action: | | Date: _____ |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|---------------------|---|-------|-----------------|
| Type: Bradenhead | # | | corrective date |
| Comment: | No bradenhead access apparent. | | |
| Corrective Action: | Install bradenhead access and/or means of monitoring bradenhead pressure. | Date: | 07/23/2021 |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Gas meter calibration record not legible or conspicuously displayed at meter. | | |
| Corrective Action: | Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2). | Date: | 07/05/2021 |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| | | | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

Inspector Name: Waldron, Emily

| | | | | | |
|--------------------|--|---------------------|---------------------|-------------|------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | Inadequate | | | Inadequate | |
| Comment: | No berm on tank. | | | | |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 603.o. | | | Date: | 07/23/2021 |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 223186 | Type: | WELL | API Number: | 081-06548 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 689805931 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5462906 |