



Photo#1:
Overview of Location from entry, view to Northwest.

June 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Pan American PA USA Atlantic Ref API#0103-07077



Photo#2:
View East over Location center.



Photo#3:
East side fill slope .

June 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Pan American PA USA Atlantic Ref API#0103-07077



Photo#4:
Access road has grown in.



Photo#5:
Debris remaining on site.

June 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Pan American PA USA Atlantic Ref API#0103-07077