

**Reportable Release Photographic Documentation**

North Carracas 32-4 #7F-3 – 6/23/2021

Looking North: Footprint of release that was outside of the flow back tank's secondary containment.



Looking West: Some of the release was contained within the flow back tank's secondary containment and was able to be recovered.

