



**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	sign at battery does not indicate wells or other information required by Rule 605.e(2)		
Corrective Action:	comply with rule 605 e for signs at battery 605.e(2)E. Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well(s); and 605.e(2)F. Location, including the quarter/quarter section, of the Tank battery.	Date:	07/27/2021

**Emergency Contact Number:**

Comment:	well sign has contact information	Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	weeds over much of location		
Corrective Action:	Comply with Rule 606	Date:	07/05/2021

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#		corrective date
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	BV CONCRETE		
Comment:	concrete vault was reported as leaking in 1998 report from Operator (document 2542826) and no record of removal of buried produced water vault can be found in COGCC records. concrete vault does not appear to be used				

Corrective Action:	<p>per rule 608.f(3)                  Operators will inspect or test buried or partially buried Tanks, vessels, or structures for leaks at least annually. Operators will maintain records documenting tests conducted pursuant to this Rule 608.f.(3) for 5 years, and provide the records to the Director upon request.                  Test of vault must be conducted within 21 days of this notice with a minimum notice to COGCC of 48 hours prior to test.                  If concrete vault is to be removed an initial form 27 must be submitted for approval on or before the corrective action date specified for test with removal of unused equipment required within 90 days of this inspection.</p>	Date:	07/19/2021
--------------------	--	-------	------------

**Paint**

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			Inadequate
Comment:	earthen berm breached and not repaired			
Corrective Action:	ensure adequate secondary containment around the produced water and crude oil storage vessels			Date: 07/28/2021

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 239987 Type: WELL API Number: 123-07775 Status: PR Insp. Status: EIFacility ID: 480225 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601413	pumpjack and wellhead sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5466182">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5466182</a>
697601414	battery sign, no wells indicated	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5466183">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5466183</a>
697601415	weeds arund heated separator	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5466184">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5466184</a>