

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/02/2021

Submitted Date:

06/22/2021

Document Number:

689805908

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
312980 _____ Waldron, Emily _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10407

Name of Operator: ANTLER ENERGY LLC

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

3 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Evans, Clay		antlerenergy@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223154	WELL	PR	08/13/1996	OW	081-06516	AMOCO-FEDERAL 20-9	PR

General Comment:

Routine FIU inspection. Compliance issues observed:
 stained soil at wellhead and pump jack motor
 pit without permit in tank battery without 2 feet of freeboard and with oil
 no label on one tank
 produced volumes are required to be reported accurately from the wellhead meter every month, and the form 7 reporting does not reflect that accurate measurement

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	One tank missing label.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/21/2021
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	307-380-7616		
Corrective Action:		Date:	_____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at wellhead and pump jack motor.		
Corrective Action:	Comply with Rule 606. Properly dispose of oily waste in accordance with 905.e.	Date:	07/07/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type:	#		corrective date
Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Vertical Heated Separator	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 223154 Type: WELL API Number: 081-06516 Status: PR Insp. Status: PR

Producing Well

Comment: Produced volumes are required to be reported accurately from the wellhead meter every month, and the form 7 reporting does not reflect that accurate measurement.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 07/21/2021

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402726808	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5461680
689805909	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5461674