

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2021

Submitted Date:

06/22/2021

Document Number:

693505232**FIELD INSPECTION FORM**Loc ID 320071 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Medina, Justin		justin.medina@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202495	WELL	SI	12/01/2019	GW	001-07900	CHAMPLIN 485 AMOCO 1	SI

General Comment:[Inspection due to complaint Doc#200449751](#)

Location				
Lease Road:				
Type	Access			
comment:	Access road to well site weeds are starting to grow.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	Adequate			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Produced water tank NFPA placards are faded and need to be replaced.			
Corrective Action:	Install sign to comply with Rule 605.g.			Date: 07/22/2021
Type	WELLHEAD			
Comment:	Sign not posted or information inaccurate at well(s)			
Corrective Action:	Install sign to comply with Rule 605.d.			Date: 07/22/2021
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Mechanical issues: Electric panels in disrepair, Well head leaking at time of inspection see video.			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.			Date: 07/22/2021
Type	OTHER			
Comment:	No BMP's in place to control sediment from pit berm from leaving location.			
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C			Date: 07/22/2021
Type	WEEDS			
Comment:	Weeds on well site, and on facility location.			
Corrective Action:	Comply with Rule 606			Date: 07/22/2021
Type	UNUSED EQUIPMENT			
Comment:	Electric panels in disrepair not able to operate.			
Corrective Action:	Comply with Rule 606			Date: 07/22/2021
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Vertical Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Electric panels			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		,

Comment:	Gauge hatch open or not sealed.	
Corrective Action:	Close and seal gauge hatches when not accessing tank per Rule 608.a.(9).	Date: 07/22/2021

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202495 Type: WELL API Number: 001-07900 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI Last production was 11-1-19. Form 4 on file with the COGCC for Alternative MIT.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 03/12/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 29 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday June 21, 2021 at approximately 2:00PM, I, Inspector Randy Silver, Conducted an on-site inspection due to a complaint Doc#200449751.</p> <p>Location: Champlin 485 Amaco #1</p> <p>Operator: Renegade oil and Gas Company.</p> <p>API#:001-07900</p> <p>County: Adams</p> <p>While there, I observed a SI well site and production facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment: Rule 606 Corrective action date of 7-22-21 See photo 3</p> <p>Mechanical issues: Rule 605e Corrective action date of 7-22-21 See photos 2,3,4</p> <p>Weeds: Rule 606 Corrective action date of 7-22-21 see photos 1,2,3,4,5,6,7</p> <p>BMP's: Rule 1002 f Corrective action date of 7-22-21 See photos 11,12</p> <p>Placards: Rule 605 Corrective action date of 7-22-21 See photo 8</p> <p>Signage: Rule 506d Corrective action date of 7-22-21 See photo 2</p> <p>Gauge hatch: Rule 608 a (9) Corrective action date of 7-22-21 See photo 17</p> <p>Weather conditions: Cloudy and dry.</p> <p>I spoke with Edward Ingvie on 6-22-21 at 11:30AM to inform the well head was leaking at time of inspection. I also informed him of the other compliance issues I observed with are in this report. This inspection is due to a complaint about debris in drainage ditch on back side of facility pit. It appears this is an old dump site not caused by the facility.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	06/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402726518	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5461420
693505233	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5461418
693505234	Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5461419