

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/21/2021

Submitted Date:

06/23/2021

Document Number:

690201700

FIELD INSPECTION FORM

Loc ID 320975 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
LEVENGOD JOHN		jlevengood07@gmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205636	WELL	PR	07/16/1987	GW	009-06047	STATE OF COLORADO 1-15	RI

General Comment:

This is a follow up of the previous inspection #690201501.
Previous inspection corrective actions have not been completed.
See attached photos and additional details within this report.

Operator is directed to perform corrective actions outlined on this inspection report immediately.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	The tank label does not comply with 605. Missing tank NFPA labeling and missing INFO.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/05/2021

Emergency Contact Number:

Comment:	The well sign does not comply with 605. Invalid Operator Emergency number. Operator Name was updated.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/05/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	The fencing around the pumpjack was repaired but the fencing around the tank was not. The fence panel is still laying on the ground.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	05/20/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	1	200 BBLs	Open Top		
Comment:	The netting on the tank has been repaired.				
Corrective Action:				Date:	

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
	Inadequate			Inadequate	
Comment:	There is inadequate secondary containment around the tank.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date:	06/03/2021

Venting:

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402727308	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5462118
690201702	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5462108