

Inspection Photos  
Operator: Morningstar Res.  
API: 007-06242  
Date: 6/29/2021



Photo 1. View the project area from the northeastern corner facing center.



Photo 2. View the eastern project area from the northeastern corner facing southward. Revegetation is comprised of rubber rabbitbrush, crested wheatgrass, and western wheatgrass.





Photos 3/4. View of tamarisk trees (approx. 10) becoming established within the well pad disturbance and along the access road.



Photo 5. View of perennial pepperweeds along the access road that need to be controlled. Approximately 500 individuals observed.



Photo 6. View of reference area comprised of irrigated grass field with grasses such as western wheatgrass, and foxtail barley, forbs such as wormwood, sedges, and cattails.