

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Gas Meter Run

1

corrective date

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Bradenhead

1

Comment: is plumbed to surface

Corrective Action:

Date:

Type: Compressor

1

Comment: PHOTO 4: SOUND MITIGATION DEVICE (MUFFLER) IS NOT INSTALLED CORRECTLY (EXHAUST PIPE FROM MUFFLER IS SMALLER THAN EXHAUST PIPE FROM MOTOR IS ALLOWING SOUND AND EXHAUST TO BYPASS MUFFLER).

Corrective Action: **INSTALL SOUND MITIGATION DEVICE (MUFFLER)**

Date: 07/08/2021

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 277817 Type: WELL API Number: 071-08382 Status: PR Insp. Status: PR

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: TOM BEARDSLEE
 Complaint Received
 Date: 6-24-21
 Complaint Contacted:
 Date: 6-28-21 Time: 13:36PM via phone left voice mail, complainant called back.
 Location ID #308639
 Location name: SPIRIT MOUNTAIN 32-28
 Inspection Document # 6935104513
 Complaint Document #200449755
 Nature of Complaint: NOISE
 Field Inspector Actions:
 On 6-24-21, I Tom Beardslee area field inspector was assigned a complaint received by COGCC staff in reference to noise. The complainant (Dennis Scheider 23017 Eagle Ct., Aguilar, CO 81020) stated the issues were occurring outside of complainants home.
 On 6-28-21 I attempted to perform a complete site inspection of the oil and gas location and associated wells in the area. Was unable to perform sound study due to weather conditions.
 On 7-7-21 I was able to perform a complete inspection of the oil and gas location and associated wells in the area. COGCC noise survey results indicate noise levels exceed limits in Rule 423.(due to terrain sound meter was set 63' to the north of source, calculated db was 68.9 I also observed a mechanical issue on the sound mitigation device (muffler) installed on compressor motor. See inspection Doc. #6935104513 for details.
 Weather conditions: 63 degrees, clear skies
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action: **Comply with Rule 423. Identify and install control measures.**

Date: 07/08/2021

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104514	SOUND STUDY RESULTS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5472791
695104515	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5472792