



Inspection Photos
Pit 117422
REM Project # 15107
Inspection Date: 6/14/2021
All Photos taken by Kris Neidel

Photo #1 Sign at entry to location



Inspection Photos
Pit 117422
REM Project # 15107
Inspection Date: 6/14/2021
All Photos taken by Kris Neidel



Photo #2 contaminated soil at wellhead.

Inspection Photos
Pit 117422
REM Project # 15107
Inspection Date: 6/14/2021
All Photos taken by Kris Neidel



Photo #3 close up of wellhead.



Inspection Photos
Pit 117422
REM Project # 15107
Inspection Date: 6/14/2021
All Photos taken by Kris Neidel



Photo #4 motor drive for Pumpjack.



Inspection Photos
Pit 117422
REM Project # 15107
Inspection Date: 6/14/2021
All Photos taken by Kris Neidel



Photo #5 sample location inside pit

Inspection Photos
Pit 117422
REM Project # 15107
Inspection Date: 6/14/2021
All Photos taken by Kris Neidel



Photo #6 pit, note: old, downed fencing containing pit.

Inspection Photos

Pit 117422

REM Project # 15107

Inspection Date: 6/14/2021

All Photos taken by Kris Neidel



Photo #7 unlabeled tank and other stored equipment. Tank appeared to be empty.