

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2021

Submitted Date:

07/09/2021

Document Number:

693700833**FIELD INSPECTION FORM**Loc ID 323578 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Axelson, John		john.axelson@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245427	WELL	SI	04/01/2021	OW	123-13222	LONGMONT FARMS UNIT 5	EI
479267	SPILL OR RELEASE	AC	01/29/2021		-	Longmont Farms Unit #5 Flowline	EI

General Comment:[COGCC Inspection of Spill ID 479267 and followup to Field Inspection Report 693700804.](#)

Inspected Facilities									
Facility ID:	245427	Type:	WELL	API Number:	123-13222	Status:	SI	Insp. Status:	EI
Facility ID:	479267	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: No Operator personnel or equipment onsite at time of inspection. Inspection is open with approximate dimensions of 50'W x 60'L x 20'D. No water is present in the excavation. Ends of flowline are exposed in the north and south walls of excavation. Cattle panel fence is down on south side of excavation. Bermed area of oily waste from last inspection has been removed. Apparent clean overburden of 50 cubic yards is staged east of excavation. What appears to be a 1" diameter piezometer has been installed adjacent the east side of the excavation.

Corrective Action: Operator to submit Form 27 with Site Investigation and Remediation Workplan for remediation of Spill (this was due by April 19, 2021). Form 27 shall include any confirmation soil sample results collected to date, proposed schedule for further remediation activity, confirmation samples of clean overburden, boring log and well construction diagram with groundwater analytical results for piezometer installed. Operator also to submit Form 19 Supplemental Report with root cause and corrective action for flowline failure and resolution of Spill via Work proceeding under a Form 27. Operator to submit results of flowline repair pressure test on Form 19 Supplemental Report.

Date: 04/28/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ **Wildlife Protection Devices (fired vessels):** _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700838	Longmont Farms Unit 5 Farms 7-9-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475578