

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2021

Submitted Date:

07/09/2021

Document Number:

700702943**FIELD INSPECTION FORM**Loc ID 316215 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|---------------------------------------|-----------------------------|
| Dooling, Jessica | 832-624-0810 | jessica.dooling@exxonmobil.com | |
| clark, Erin | 405-319-3250 | erin.k.clark@exxonmobil.com | Lead regulatory coordinator |
| , Caerus | | COGCC.inspections@caerusoilandgas.com | |
| Sutton, Derek | | derek_sutton@xtoenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 257264 | WELL | PR | 03/01/2021 | GW | 103-10019 | LOVE RANCH FEE 3 | PR |

General Comment:**COGCC Inspection Report Summary**

On Wednesday 7/7/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at XTO/Caerus Love Ranch #3, at Location # 316215 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Location shows signs of lack of stabilization/compaction
2. Well head cellars do not provide egress for wildlife
3. Random debris
4. Cellar full of fluid

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|-----|-------------|
| Comment: | 911 | |
| Corrective Action: | | Date: _____ |

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | OTHER | | |
| Comment: | Well head cellars do not provide egress for wildlife and full of fluid | | |
| Corrective Action: | Install means of egress or eliminate wildlife access and evacuate fluids. | Date: | 07/23/2021 |
| Type | DEBRIS | | |
| Comment: | Random debris (hose at well head) | | |
| Corrective Action: | remove debris | Date: | 07/23/2021 |

Overall Good: ☐**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|---------------------------|---|-------|-----------------|
| Type: Plunger Lift | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | chemical tank at well head in metal containment | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | | |
|-----------------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 257264 | Type: WELL | API Number: 103-10019 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | producing | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Ditches | | | | |
| Berms | | | | | | |
| Compaction | Fail | | | | | |
| Ditches | | | | | | |
| | | Culverts | | | | |

Comment: 1. Location shows signs of lack of stabilization/compaction

Corrective Action: Install or repair required BMPs

Date: 08/09/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 700702956 | photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475608 |