

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 1. Debris migrating off location.



Photo 2. Debris on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194




Photo 3. Debris on location.



Photo 4. Debris and equipment storage on location.



Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 5. Debris and equipment storage on location.



Photo 6. Debris and equipment storage on location.



Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 7. Debris and equipment storage on location.



Photo 8. Debris and equipment storage on location.



Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 9. Debris and equipment storage on location.



Photo 10. Debris and equipment storage on location.



Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 11. Debris and equipment storage on location.



Photo 12. No wellhead sign. No bradenhead access apparent.

